


Overall View – 6" O.D. Core x 58-1/2" Long part



Left Hand Side



Right Hand Side



Left Hand View Close-up









See photo above and below. Note the gap between the steel journal and the aluminum arbor. There are two cap screws missing (of the pattern of (6)). Someone has taken this

apart and not reassembled it properly.



